Technical Data

Effect of exposure to sulphur dioxide solutions S1, S2, S3.





Test Results	Requirements of BS EN 12326-1:2014		
Effect of exposure to sulphur dioxide solution	CODE	Sulphur Dioxide	Acceptance Criteria
	\$1	A	Shall show NO signs of spilting or cracking of the edges and swelling, softening or surface flaking.
Colour change after exposure to sulphur dioxide	S2	В	
	\$3	В	If any one or more test piece show signs of splitting or cracking of the edges and swelling, softening or surface flaking.