

TEST RESULTS	Requirements of BS EN 12326-1:2004		
	Code	Sulfur dioxide	Acceptance Criteria
Effect of exposure to sulfur dioxide solution	S1	A	Shall show NO signs of splitting or cracking of the edges and swelling, softening or surface flaking.
Colour change after exposure to sulfur dioxide	S2	B	
	S3	B	If any one or more test piece show signs of splitting or cracking of the edges and swelling, softening or surface flaking.

